

# Latest Firmware for the mObridge DA-G2 A2B

Version	2.7.0	
<b>Released On</b>	16 <sup>th</sup> July 2023	
Fixes		
<ul> <li>Addition of CAN message acceptance filtering algorithm to ensure CAN messages are never missed when sent.</li> </ul>		
<ul> <li>Mute</li> </ul>	<ul> <li>Mute audio when switching presets to avoid unwanted artifacts.</li> </ul>	
<ul> <li>Adjus</li> </ul>	<ul> <li>Adjust volume mapping table for better DSP gain responsiveness.</li> </ul>	
<ul> <li>Nume</li> </ul>	Numerous Ford volume decoding and phone call handling improvements to better emulate the original	

 Numerous Ford volume decoding and phone call handling improvements to better emulate the original OEM amplifier, and ensure phone call mode does not get stuck.

• Further fixes for pops on firmware update.

### **Updating Your Firmware**

Your mObridge DA-G2 product is fully firmware updatable and can be updated in the following ways:

#### Via mObridge DSP:

Download and install mObridge DSP from mobridge.us/mobridge-dsp-pc-application

#### Via mObridge Updater:

Download and install mObridge Updater from mobridge.us/firmware-update/

Refer to our website at <u>mobridge.us</u> for further information.



Past Firmware versions		
Version	2.6.9	
Released On	18 <sup>th</sup> May 2022	
Fixes		
Some performance optimizations.		
Correcting left and right inputs.		
• Using audio on message on place of ignition message to turn on remote amp enable. This ensures that		

## Past Firmware Versions

audio does not cut out on ignition off, but rather when the driver's door is opened.

Turn off remote amp enable prior to updating firmware to avoid popping. •

Version	2.6.7
Released (	6 <sup>th</sup> December 2021
Fixes	
Adding Ford F150 acessories ignition CAN message.	
• Fixing pops when flash updating. Properly turn off amplifier remote signal when flash updating.	

Version	2.5.5
Released On	3 <sup>rd</sup> November 2021
Fixes	
Fixing issue with Ford ignition CAN status messages.	
Update A2B stack.	
<ul> <li>Revised default input gains and output gains to ensure full range is achieved.</li> </ul>	

Version	2.5.4	
Released On	8 <sup>th</sup> July 2021	
Fixes		
Fixing MDI null app name issue.		

Version	2.5.3	
Released On	5 <sup>th</sup> July 2021	
Fixes	Fixes	
Fixed stack overflow issue regarding DSP core.		
Fixed issue with input delay array overrun.		

Version	2.5.2	
Released On	16 <sup>th</sup> April 2021	
Fixes		
Fixed TOSLINK Tx on baseboard rev 3.0		

Version	2.5.1	
Released On	18 <sup>th</sup> February 2021	
Fixes		
<ul> <li>Fixing logical input gain index mismatch with mObridge DSP.</li> </ul>		
Revamped logging type names.		
Added support for AT25SF321B SPI flash chip.		

Version 2.5.0



Released On	25 <sup>th</sup> January 2021
Fixes	
Further fixes for Ford A2B/CAN sleeping issues.	

Version	2.4.2	
Released On	4 <sup>th</sup> January 2021	
Fixes		
<ul> <li>Fixing issue with improper MDI communications for IIR Biquad filtering.</li> </ul>		

Version	2.4.1	
Released On	23 <sup>rd</sup> December 2020	
Fixes		
• Fixing further Ford A2B vehicle sleeping issues.		

Version		2.4.0
Released On		27 <sup>th</sup> November 2020
Fixes		
• Sub-woofers/Woofers now use IIR filtering only for the channel EQ to improve low range frequency response, and its precision when tuning.		
•	<ul> <li>Vastly improved THD on Sub-woofer/Woofer channels.</li> </ul>	
<ul> <li>Various performance entimizations to the DCD serve</li> </ul>		

- Various performance optimizations to the DSP core. •
- Fixes for Ford vehicle wakeup signals.

	Version	
	Released On	
Fixes		
Major overhaul of Ford vehicle compatibility module.		

Version	0.5.6	
Released On	23 <sup>rd</sup> March 2020	
Fixes		
Initial Release		

