

# Latest Firmware for the mObridge DA-G2 A2B

Version	2.8.2
Released On	12 <sup>th</sup> January 2024
Fixes	
Fixing distorted phone, nav, beeps, voice prompt sources regression issue.	

## **Updating Your Firmware**

Your mObridge DA-G2 product is fully firmware updatable and can be updated in the following ways:

#### Via mObridge DSP:

Download and install mObridge DSP from mobridge.us/mobridge-dsp-pc-application

#### Via mObridge Updater:

Download and install mObridge Updater from <a href="mobridge.us/firmware-update/">mobridge.us/firmware-update/</a>

Refer to our website at mobridge.us for further information.

#### **Past Firmware Versions**

Version	2.8.1	
Released On	11 <sup>th</sup> January 2024	
Fixes		
Additional speed optimizations to Ford DSP layer.		
<ul> <li>Fixing t</li> </ul>	<ul> <li>Fixing turn off/on pops.</li> </ul>	

Version	2.7.2	
Released On	27 <sup>th</sup> September 2023	
Fixes		
<ul> <li>Update DSP gain scaling to new re-adjusted levels. Requires mObridge DSP 23.08.04 or later to use.</li> </ul>		
<ul> <li>Additi</li> </ul>	<ul> <li>Addition of DRC limiting calibration to maximum allowed voltage.</li> </ul>	

•	Some flash memory safeguards introduced.	

Version	2.7.0
Released On	16 <sup>th</sup> July 2023

#### **Fixes**

- Addition of CAN message acceptance filtering algorithm to ensure CAN messages are never missed
- Mute audio when switching presets to avoid unwanted artifacts.
- Adjust volume mapping table for better DSP gain responsiveness.
- Numerous Ford volume decoding and phone call handling improvements to better emulate the original OEM amplifier, and ensure phone call mode does not get stuck.
- Further fixes for pops on firmware update.

Version	2.6.9
Released On	18 <sup>th</sup> May 2022
Eivos	

- Some performance optimizations.
- Correcting left and right inputs.
- Using audio on message on place of ignition message to turn on remote amp enable. This ensures that audio does not cut out on ignition off, but rather when the driver's door is opened.
- Turn off remote amp enable prior to updating firmware to avoid popping.

Version	2.6.7	
Released On	6 <sup>th</sup> December 2021	
Fixes		
Adding Ford F150 acessories ignition CAN message.		
<ul> <li>Fixing p</li> </ul>	<ul> <li>Fixing pops when flash updating. Properly turn off amplifier remote signal when flash updating.</li> </ul>	

Version	2.5.5
Released On	3 <sup>rd</sup> November 2021
Fixes	

### Fixing issue with Ford ignition CAN status messages.

- Update A2B stack.
- Revised default input gains and output gains to ensure full range is achieved.

Version	2.5.4
Released On	8 <sup>th</sup> July 2021
Fixes	



• Fixing MDI null app name issue.

Version	2.5.3	
Released	I <b>On</b> 5 <sup>th</sup> July 2021	
Fixes		
Fixed stack overflow issue regarding DSP core.		
	Fixed issue with input delay array overrun	

Version	2.5.2
Released On	16 <sup>th</sup> April 2021
Fixes	
Fixed TOSLINK Tx on baseboard rev 3.0	

Version	2.5.1	
Released On	18 <sup>th</sup> February 2021	
Fixes		
Fixing logical input gain index mismatch with mObridge DSP.		
Revamped logging type names.		
Added si	<ul> <li>Added support for AT25SF321B SPI flash chip.</li> </ul>	

Version	2.5.0
Released On	25 <sup>th</sup> January 2021
Fixes	
<ul> <li>Further fixes for Ford A2B/CAN sleeping issues.</li> </ul>	

Version	2.4.2	
Released On	4 <sup>th</sup> January 2021	
Fixes		
Fixing issue with improper MDI communications for IIR Biquad filtering.		

Version	2.4.1
Released On	23 <sup>rd</sup> December 2020
Fixes	
Fixing further Ford A2B vehicle sleeping issues.	

Version	2.4.0
Released On	27 <sup>th</sup> November 2020
Fixes	

- Sub-woofers/Woofers now use IIR filtering only for the channel EQ to improve low range frequency response, and its precision when tuning.
- Vastly improved THD on Sub-woofer/Woofer channels.
- Various performance optimizations to the DSP core.
- Fixes for Ford vehicle wakeup signals.

Version	2.3.0
Released On	30 <sup>th</sup> October 2020
Fixes	
Major overhaul of Ford vehicle compatibility module.	



Version	0.5.6	
Released On	23 <sup>rd</sup> March 2020	
Fixes		
Initial Release		

