

## [24.06.01] - 2023-06-17

#### Changed

- Fixing issue where firmware update check gets stuck indefinitely.
- Fixing macOS device screen display issue.
- Fixing intermittent issue where if multiple mObridge devices are connected, the input gains are empty for one of them.

## [24.06.00] - 2023-06-12

### Changed

- Fixing intermittent issue where if multiple mObridge devices are connected, the input gains and channels selections are empty for one of them.
- Fixing issue where firmware update check gets stuck indefinitely.
- Fixing macOS device screen display issue.
- Do not fetch latest firmware releases if firmware has a stable release marked.
- Fixing Qt issues on upgrade to 6.7.0
- Fixing dialog window shrinking on main window movement.

## [24.04.00] - 2023-04-17

- Adding MOST25 vehicle specific logical input labels.
- Reducing minimum input gains to -48 dB.
- Fixing issue where channel is incorrectly muted on device connection.
- Fixed issue where factory reset hangs forever.
- Extended flash timeout.
- Add timeout to factory reset, reset functions to ensure hang-free operation.





- Adding missing OEM products.
- Fixing scaling and text placement issues in macOS since Qt6 port.
- Fixing bundled firmware directory location.

## [23.12.00] - 2023-12-19

#### Changed

- Ensure vehicle selection does not change between firmware updates.
- Fix incorrect BMW input labels
- Removed unused Ftdi CDM driver from Windows installer.

## [23.11.00] - 2023-11-08

### Changed

- Additional Qt6 support for macOS
- Minimum macOS is now Catalina 10.15, as Qt6 mandates this.

## [23.10.00] - 2023-10-06

#### Added

- Support for the latest products.
- User-interface improvements, Windows scaling handling via Qt6.
- Move to 64-bit Windows.





## [22.07.00] - 2022-07-13

#### Added

• Support for MOST150 oPHY/cPHY and A2B Ford K2 DSP/amplifiers.

## [22.06.00] - 2022-06-23

#### Added

• Support for 16-bit filter bins.

# [22.05.00] - 2022-05-09

### Changed

Fixes for macOS Monterrey.

# [22.03.02] - 2022-03-17

#### Added

• Support for scaling on high DPI screens.

- Fixed LW console debug log copy, save, and backspace issues.
- New debug console font.
- Fixing issue with licence file packaging.





[22.03.01] - 2022-03-11

## Changed

• Addition of LW debug enable message

[22.03.00] - 2022-03-07

### Changed

Fixing connect issue with misc. products.

[22.02.03] - 2022-02-25

#### Added

- Adding ability to change devices, debug console for developers.
- Adding recovery panel for devices in recovery mode.

#### Changed

Fixing missing Options and Tools menu in 21.11.00

# [21.11.00] - 2021-11-05

#### Changed

• Fixing automatic updater module incorrectly choosing manual update.





### [21.10.00] - 2021-10-28

## Changed

• Adding product support for M1 amp, and latest DSP app version.

## [21.09.00] - 2021-09-10

### Changed

• Fixing broken product connectivity with legacy products.

# [21.08.00] - 2021-08-18

### Changed

Fixing broken auto firmware updater URL, as webserver is now redirecting links.

# [21.07.02] - 2021-07-08

#### Changed

• Fixing zero-length string for DSP settings 'name' field.

# [21.07.01] - 2021-07-05

#### Changed

Minor bugfixes, routine release.





# [21.06.00] - 2021-06-10

## Changed

• Fixes for broken vehicle selector.

## [21.05.02] - 2021-05-21

### Changed

- Fixes for macOS on Big Sur
- Fixes for M2 series Bluetooth configuration options.

## [21.05.01] - 2021-05-14

#### Added

- Fixing DA-G2 A2B Standard feature compatibilities.
- Fixing broken UI loading spinner.

# [21.05.00] - 2021-05-06

#### Added

• Support for OBD Coding Tool (BMW) products.

# [21.04.00] - 2021-04-26

#### Added

• Support for DA-G2 MOST150 COAX product range.





## [21.03.01] - 2021-03-26

#### Added

• Re-adding Porsche PCM3.x vehicle option.

## [21.03.00] - 2021-03-18

#### Added

- Support for LW updater protocol.
- Support for ATSAM products.

### Changed

• User interface tweaks and improvements.

# [21.02.01] - 2021-02-19

#### Changed

• Support for logical inputs versus input channels.

# [21.02.00] - 2021-02-09

- Fixed main window sizing issues for certain products.
- Fixed Bluetooth form issues for M2 series of products.
- Fixed the MOST bypass switch UI functionality.





## [21.01.00] - 2021-01-29

## Changed

- Minor bugfixes
- Updated product descriptions and images

## [20.11.00] - 2020-11-18

#### Added

• Biquad IIR cascaded filtering support

# [20.10.01] - 2020-10-14

## Changed

Fixed misnamed Windows shortcuts and Start menu entries.

# [20.10.00] - 2020-10-06

#### Added

• Initial macOS release.

- Fixed missing logo on version information dialog.
- Fixed misnamed Windows shortcuts and Start menu entries.





## [20.09.02] - 2020-09-30

## Changed

• Addition of 16-bit gains for DSP-enabled products.

## [20.09.01] - 2020-09-15

### Changed

• Fixing issue with vehicle selection.

# [20.09.00] - 2020-09-09

### Changed

Support for Bluetooth version on M2 products

# [20.08.01] - 2020-08-26

#### Added

• Support for mObridge DAB products

### Changed

• Various user interface improvements

# [20.08.00] - 2020-08-19

#### Added

• Initial release

