



## [23.12.00] - 2023-12-19

### Changed

- Ensure vehicle selection does not change between firmware updates.
- Fix incorrect BMW input labels
- Removed unused Ftdi CDM driver from Windows installer.

## [23.11.00] - 2023-11-08

### Changed

- Additional Qt6 support for macOS
- Minimum macOS is now Catalina 10.15, as Qt6 mandates this.

## [23.10.00] - 2023-10-06

### Added

- Support for the latest products.
- User-interface improvements, Windows scaling handling via Qt6.
- Move to 64-bit Windows.

## [22.07.00] - 2022-07-13

### Added

- Support for MOST150 oPHY/cPHY and A2B Ford K2 DSP/amplifiers.



## [22.06.00] - 2022-06-23

### Added

- Support for 16-bit filter bins.

## [22.05.00] - 2022-05-09

### Changed

- Fixes for macOS Monterrey.

## [22.03.02] - 2022-03-17

### Added

- Support for scaling on high DPI screens.

### Changed

- Fixed LW console debug log copy, save, and backspace issues.
- New debug console font.
- Fixing issue with licence file packaging.

## [22.03.01] - 2022-03-11

### Changed

- Addition of LW debug enable message



## [22.03.00] - 2022-03-07

### Changed

- Fixing connect issue with misc. products.

## [22.02.03] - 2022-02-25

### Added

- Adding ability to change devices, debug console for developers.
- Adding recovery panel for devices in recovery mode.

### Changed

- Fixing missing Options and Tools menu in 21.11.00

## [21.11.00] - 2021-11-05

### Changed

- Fixing automatic updater module incorrectly choosing manual update.

## [21.10.00] - 2021-10-28

### Changed

- Adding product support for M1 amp, and latest DSP app version.



## **[21.09.00] - 2021-09-10**

### **Changed**

- Fixing broken product connectivity with legacy products.

## **[21.08.00] - 2021-08-18**

### **Changed**

- Fixing broken auto firmware updater URL, as webserver is now redirecting links.

## **[21.07.02] - 2021-07-08**

### **Changed**

- Fixing zero-length string for DSP settings 'name' field.

## **[21.07.01] - 2021-07-05**

### **Changed**

- Minor bugfixes, routine release.

## **[21.06.00] - 2021-06-10**

### **Changed**

- Fixes for broken vehicle selector.



## [21.05.02] - 2021-05-21

### Changed

- Fixes for macOS on Big Sur
- Fixes for M2 series Bluetooth configuration options.

## [21.05.01] - 2021-05-14

### Added

- Fixing DA-G2 A2B Standard feature compatibilities.
- Fixing broken UI loading spinner.

## [21.05.00] - 2021-05-06

### Added

- Support for OBD Coding Tool (BMW) products.

## [21.04.00] - 2021-04-26

### Added

- Support for DA-G2 MOST150 COAX product range.

## [21.03.01] - 2021-03-26

### Added

- Re-adding Porsche PCM3.x vehicle option.





## [21.03.00] - 2021-03-18

### Added

- Support for LW updater protocol.
- Support for ATSAM products.

### Changed

- User interface tweaks and improvements.

## [21.02.01] - 2021-02-19

### Changed

- Support for logical inputs versus input channels.

## [21.02.00] - 2021-02-09

### Changed

- Fixed main window sizing issues for certain products.
- Fixed Bluetooth form issues for M2 series of products.
- Fixed the MOST bypass switch UI functionality.

## [21.01.00] - 2021-01-29

### Changed

- Minor bugfixes
- Updated product descriptions and images



## **[20.11.00] - 2020-11-18**

### **Added**

- Biquad IIR cascaded filtering support

## **[20.10.01] - 2020-10-14**

### **Changed**

- Fixed misnamed Windows shortcuts and Start menu entries.

## **[20.10.00] - 2020-10-06**

### **Added**

- Initial macOS release.

### **Changed**

- Fixed missing logo on version information dialog.
- Fixed misnamed Windows shortcuts and Start menu entries.

## **[20.09.02] - 2020-09-30**

### **Changed**

- Addition of 16-bit gains for DSP-enabled products.



**[20.09.01] - 2020-09-15**

**Changed**

- Fixing issue with vehicle selection.

**[20.09.00] - 2020-09-09**

**Changed**

- Support for Bluetooth version on M2 products

**[20.08.01] - 2020-08-26**

**Added**

- Support for mObridge DAB products

**Changed**

- Various user interface improvements

**[20.08.00] - 2020-08-19**

**Added**

- Initial release