

# Latest Firmware for mObridge MOST25 8.1.1 Amplifier:

Version	0.7.1
Release Date	15 <sup>th</sup> August 2023

#### Fixes

- Update amplifier controller to allow power rail offset via vehicle stereo input volume.
- Add fade-out of audio when selecting presets.
- Remove preset switch notify to head-unit on MOST, as this interferes with audio fade-in/out on preset switching.
- Improvements to reduce the likelihood of pops when resetting the system.

### **Updating Your Firmware**

Your mObridge MOST25 8.1.1 Amplifier is fully firmware updatable and can be updated in the following ways:

#### Via mObridge DSP:

Download and install mObridge DSP from mobridge.us/mobridge-dsp-pc-application

#### Via mObridge Updater:

Download and install mObridge Updater from mobridge.us/firmware-update/

Refer to our website at <u>mobridge.us</u> for further information.



### **Past Firmware Versions**

Version	0.7.0
Release Date	9 <sup>th</sup> May 2023

#### Fixes

- Additional boosting to stereo source.
- Amplifier power booster has a much faster response time, reducing the potential to clip
- Vast reduction of startup/shutdown speaker pops.
- Fixing pops on firmware update.
- Fixing factory default channel mapping
- Fixing centre-channel upmix inavailability.

Version	0.6.4
Release Date	8 <sup>th</sup> August 2022
Fixes	
Additional 6dB boost to input sources.	
<ul> <li>Fixing the amplifier controller firmware booster voltage ramping.</li> </ul>	

Version	0.6.2
Release Date	5 <sup>th</sup> August 2022
Fixes	
Fixing communication issues, with baseboard amplifier firmware.	

Version	0.6.0	
Release Date	24 <sup>th</sup> June 2022	
Fixes		
Fixing incorrect L/R input mismatch.		
Experimental 16-bit streamlined processing.		
<ul><li>Vast</li></ul>	Vastly improve the FFT resolution.	

Version	0.5.18
VEISIOII	0.5.18

## Release Date 0.5.18 Release Date 25<sup>th</sup> May 2022

#### Fixes

• Frequency response correction implemented.

Major performance improvements to the DSP core.

Rework Jaguar, Land Rover G2 volume mapping to have more range.

Performance enhancements for Mercedes-Benz NTG vehicles.

- Additional support for Jaguar vehicles requiring two MOST25 amplifier instances.
- Fixing Audi MMI3G subwoofer regression issue.

Version	0.5.15
Release Date	7 <sup>th</sup> April 2022
Fixes	
	(-)

- Addition of Dynamic Range Compression (DRC).
- Addition of per-channel user-set limits.
- Addition of feedback channel RMS values to mObridge DSP.
- Extend Maximum IIR Biquad points to 16.

Version	0.5.12
Release Date	31 <sup>st</sup> August 2021
Fixes	



- Update amplifier controller firmware to resolve issues with voltage spikes at startup.
- Fixing issues with MOST ConfigNok message causing no audio.

Version	0.5.11
Release Date	7 <sup>th</sup> July 2021
Fixes	
Fixing MDI null app name issue.	

Version	0.5.10
Release Date	5 <sup>th</sup> July 2021
Fixes	
<ul> <li>Fixing potential stack overflow issue regarding DSP core.</li> </ul>	

Version	0.5.9
Release Date	16 <sup>th</sup> June 2021
Fixes	
Adding explicit Toyota Supra vehicle support for mObridge DSP and mObridge Updater	

- Fixing various BMW issues related to multichannel audio, ignition, and turn on/off time.
- Fixing issue with corrupted NVM regarding improper boundary checks on input delay field.

Version		0.5.8
Release	Date	8 <sup>th</sup> June 2021
Fixes		
•	<ul> <li>Major optimizations for baseboard power control module to enable vastly lower operating</li> </ul>	
temperatures.		
•	6dB boost to all mono channels to address quiet phone, nav, chimes, pdc audio.	

Version	0.5.6	
Release Date	24 <sup>th</sup> May 2021	
Fixes		
Fixing incorrect tick time in back-end amp controller service.		

Version	0.5.5
Release Date	24 <sup>th</sup> May 2021
Fixes	

• Remove master, head-unit, and other EQ influences from subwoofer-assigned speakers, such that they are totally EQ'ed by their respective channel EQs.

NOTE: This release decreases subwoofer attenuation, thereby increasing default subwoofer gain.

Version	0.5.4
Release Date	14 <sup>th</sup> May 2021
Fives	

- Removing unneeded attenuation on output codecs.
  - Fixing BMW loopback echo issue.
  - Fixing broken fade/balance controls in Aston Martin.
  - Fixing Porsche PCM3.x phone echo issue.
  - Fixing improper reset of input delay in NV.

NOTE: This release vastly improves output gain range.

Version	0.5.3



Release Date	26 <sup>th</sup> February 2021	
Fixes		
• Fixin	Fixing Audi MMI3G head-unit preset selection control.	
• Fixin	Fixing Audi MMI3G head-unit subwoofer gain control.	

Version	0.5.0	
Release Date	5 <sup>th</sup> February 2021	
Fixes		
Initial stable release		

